

## CHARSET -Subprogram--Set Characters

## CHARSET

## Format

CALL CHARSET

## Cross Reference

CHAR, COLOR

## Description

The CHARSET subprogram restores default character definitions and colors.

CHARSET, restores the default character definitions to characters 32-126, inclusive.

In Graphics (1) or (1,1), CHARSET restores the default colors to all 256 characters.

## CHDIR

## CHDIR

## Format

CHDIR path.filename

## Cross Reference

FILES, PWD, KEY LIST

## Description

This COMMAND allows you to change the default working directory.

## Examples

From the prompt

CHDIR DSKx.SUBDIR

CHDIR HDSx.SUBDIR.SUBDIR

Typing PWD or KEY LIST from the prompt will display the working directory.